


**LEACHATE COLLECTION WELLS
INTERIM OM&M INSPECTION SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

INSPECTOR'S NAME	INSPECTOR'S SIGNATURE	INSPECTION TIME	INSPECTION DATE
Refugio D Gutierrez			May 28 ²⁹ 2007


ITEM OF POTENTIAL CONCERN	CONDITIONS OBSERVED				COMMENTS	CHECK (✓) BELOW WHEN COMPLETED
	WELL ID LC-1	WELL ID LC-2	WELL ID LC-3	WELL ID LC-4		
Wellhead (well box, cover, gasket, concrete)	ok	ok	ok	ok		✓✓✓
Well Casing and Cap/Plug	ok	ok	ok	ok		✓✓✓
Liquid Present in Well Box	NO	NO	NO	NO		✓✓✓
Other:						
Other:						
Other:						

W:\InterimOpMain+Mon\LeachateCollection\Wells\WorkPlan+FieldForms\February2007\Feb507LC-WellsInspection(YF).doc

**LEACHATE COLLECTION WELLS
INTERIM OM&M MONITORING AND BAILING DATA SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

DATE: May ²⁹ 28, 2007

TECHNICIAN NAME: Reynold P. Gattner

TECHNICIAN SIGNATURE 

WELL ID	BOTTOM OF WELL AFTER CONSTRUCT-ED [TOTAL DEPTH] (ft)	MEASURED BOTTOM OF WELL [TOTAL DEPTH] (ft)	GAUGING TIME		DEPTH TO LIQUID (ft)						HEIGHT OF LIQUID COLUMN (ft)		VOLUME OF LIQUID REMOVED (gallons)	COMMENTS
			Start	Finish	Start			Finish			Start	Finish		
					1 st Rdg.	2 nd Rdg.	3 rd Rdg.	1 st Rdg.	2 nd Rdg.	3 rd Rdg.				
LC-1	22.25	22.25	0829	0837	19.45	19.45	19.45	21.55	21.55	21.55				
LC-2	21.90	21.90	0843	0856	13.35	13.35	13.35	20.35	20.35	20.35				
LC-3	22.20	22.20	0901	0906	21.25	21.25	21.25	21.25	21.25	21.25				
LC-4	21.90	21.88	0911	0928	11.40	11.40	11.40	21.05	21.05	21.05				

W:\InterimOpMain+Mon\LeachateCollection\Wells\WorkPlan+FieldForms\February2007\Feb507LC-WellsM&B(YF1).doc

DAILY FIELD REPORT

JOB NAME: WASTE DISPOSAL, INC. (WDI)	PROJECT NUMBER: 290316-01/1303A	5-29-07 DATE: 5/28/2007
LOCATION: Santa Fe Springs, California	WEATHER:	DAY: Monday
INTERIM OM&M CONTRACTOR: TRC	FOREMAN:	
FIELD TECHNICIAN: Refugio D. Gutierrez	INSPECTION/TESTING OF: LEACHATE MONITORING/CONTROL SYSTEM	
SUMMARY OF OPERATIONS/WORK PERFORMED::		
<p>Drive to WDI. Took water out of knock out pot. Gauged and Hand bailed Product from LC1, LC2, LC4. LC3 had less than a foot of product. Drive around checked for damage on fence. Picked up trash. Cleaned lids. Drive back to shop.</p>		
		TRC Customer-Focused Solutions

Note: Specific System Data and Observations are Included on “Interim OM&M Inspection Sheets” and “Interim OM&M Monitoring and Bailing Data Sheets”

DAILY FIELD REPORT
WASTE DISPOSAL, INC
SANTA FE SPRINGS, CALIFORNIA

TRG**FIGURE J.1**